

Executive Summary

Of

RE Component of

DDUGJY

Jan-2018

Web & MIS Group

RE DIVISION



आर ई सी
REC

असीमित ऊर्जा, अनन्त संभावनाएं
Endless energy. Infinite possibilities.

Scope & Cumulative Achievement

Projects Sanctioned under		X Plan	XI Plan	Total Phase I	XI Plan Ph-II	XII Plan	New (RE)	Others	DDG (XI, XII & New)	Stateplan	Grand Total
No. of Projects		235	341	576	72	273	636		4377		5934
Sanctioned Project Cost in Rs. Cr. (Effective cost)		12810.34	19954.75	32765.09	9363.09	23606.4	41408.77		1368.91		108512.26
Release in Rs. Cr.		12360.37	18374.63	30735.00	5779.28	11550.30	5234.81		462.40		53761.79
		96%	92%	94%	62%	49%	13%		34%		50%
Un-electrified Villages (UEV) (in Nos.)	Scope	64167	46965	111132	2207	8995	3351		3379		129064
	Ach.	63972	45959	109931	2005	6749	3177	951	1552	784	125149
	%	100%	98%	99%	91%	75%	95%		46%		97%
Intensive Electrification of Villages(IEV) (in Nos.)	Scope	97571	212606	310177	52644	231760	185883				780464
	Ach.	97084	208640	305724	38403	119545	24220				487892
	%	100%	98%	99%	73%	52%	13%				63%
BPL HH covered (in Lakhs)	Scope	76.60	145.37	221.97	44.77	132.48	36.89		1.6		437.71
	Ach.	74.51	138.99	213.5	20.48	39.25	9.41		0.58		283.22
	%	97%	96%	96%	46%	30%	26%		36%		65%

341 Projects of XI Plan Phase-I

Statewise Status of Defects Reported & Rectified under 3-Tier Quality Control Mechanism

As on 31.01.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		No. of Descrepancies Observed by TPIA	No. of Descrepancies rectified	No. of Descrepancies Observed by RQM	No. of Descrepancies rectified	No. of Descrepancies Observed by NQM	No. of Descrepancies rectified
1	Andhra Pradesh	6624	6624	1951	1951	668	668
2	Arunachal Pradesh	2615	2615	3383	3383	618	618
3	Assam	17916	17916	11912	11912	188	188
4	Bihar	40710	21828	13676	12826	1400	1151
5	Chhattisgarh	5084	5080	3913	3913	1494	1494
6	Gujarat	36686	36686	2641	2641	1667	1667
7	Haryana	18257	18257	2159	2159	447	447
8	Himachal Pradesh	1860	1860	2480	2480	2253	2253
9	J&K	11507	10866	5158	5158	318	265
10	Jharkhand	16476	16092	12549	12549	1162	1162
11	Karnataka	5204	5204	4600	4600	768	768
12	Kerala	264	264	281	281	210	210
13	MP	41306	38589	12791	12791	3451	3208
14	Maharashtra	31011	31011	4949	4949	3183	3183
15	Manipur	1707	1707	8334	700	653	164
16	Meghalaya	1730	1730	1154	1154	554	554
17	Mizoram	1079	1079	193	193	113	113
18	Nagaland	1810	1810	540	540	188	188
19	Orissa	32972	29906	2814	2814	4159	4159
20	Punjab	12406	9756	2269	2269	1051	1051
21	Rajasthan	94635	93437	28112	28112	1882	1882
22	Sikkim	6	6	274	274	50	50
23	Tamil Nadu	15145	15145	6021	6021	1142	1142
24	Tripura	643	643	266	266	142	142
25	West Bengal	49539	49539	28461	28461	2213	2213
Total		447192	417650	160881	152397	29974	28940

* No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.

72 Projects of XI Plan Phase-II

Statewise Status of Village Inspected under 3-Tier Quality Control Mechanism

As on 31.01.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		Scope of TPIA	No. of Villages Inspected	Scope of RQM	No. of Villages Inspected	Scope of NQM	No. of Villages Inspected
1	Bihar	7064	3405	2826	1310	143	125
2	Chhattisgarh	602	1076	241	241	12	5
3	Haryana	313	27	125	0	6	0
4	Karnataka	294	320	117	117	6	6
5	Kerala	247	268	128	128	7	7
6	MP	7905	6477	3162	1825	160	74
7	Maharashtra	415	684	166	166	11	11
8	Tamil Nadu	365	73	146	0	8	3
9	Uttar Pradesh	9911	9912	3964	3264	199	136
10	West Bengal	153	52	61	20	3	1
Total		27269	22294	10936	7071	555	368

1. TPIA Reports from some of the states are awaited

72 Projects of XI Plan Phase-II

Statewise Status of Defects Reported & Rectified under 3-Tier Quality Control Mechanism

As on 31.01.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		No. of Descrepancies Observed by TPIA	No. of Descrepancies rectified	No. of Descrepancies Observed by RQM	No. of Descrepancies rectified	No. of Descrepancies Observed by NQM	No. of Descrepancies rectified
1	Bihar	55998	10132	12525	3593	12424	2944
2	Chhattisgarh	3320	3320	11050	11050	659	659
3	Haryana	137	0	0	0	0	0
4	Karnataka	1890	1890	1918	1918	98	98
5	Kerala	639	639	2542	2542	131	131
6	MP	58913	55619	108991	97721	5348	4451
7	Maharashtra	1662	1662	9845	9845	219	114
8	Tamil Nadu	443	0	0	0	64	0
9	Uttar Pradesh	119511	74851	134551	85821	13702	11049
10	West Bengal	361	323	573	221	170	170
Total		242874	148436	281995	212711	32815	19616

* No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.

273 Projects of XII Plan

Statewise Status of Defects Reported & Rectified under 3-Tier Quality Control Mechanism

As on 31.01.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		No. of Descrepancies Observed by TPIA	No. of Descrepancies rectified	No. of Descrepancies Observed by RQM	No. of Descrepancies rectified	No. of Descrepancies Observed by NQM	No. of Descrepancies rectified
1	Assam	6465	1887	515	280	0	0
2	Bihar	82179	38988	28709	10813	1091	0
3	Chhattisgarh	16968	16968	6460	6460	609	499
4	J&K	0	0	0	0	0	0
5	Jharkhand	0	0	0	0	0	0
6	Karnataka	15455	15455	2989	2989	264	57
7	MP	68117	66294	65598	52166	15806	5587
8	Manipur	427	127	1291	0	0	0
9	Mizoram	232	232	57	43	0	0
10	Nagaland	0	0	126	0	0	0
11	Orissa	28664	21439	7692	4228	1705	0
12	Rajasthan	24749	20195	48308	27492	22622	6622
13	Tripura	2465	2465	1585	1107	87	0
14	Uttar Pradesh	223490	124599	68830	31388	21436	5903
15	West Bengal	20171	18670	9794	5176	1006	559
Total		489382	327319	241954	142142	64626	19227

* No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.

273 Projects of XII Plan

Statewise Status of Village Inspection under 3-Tier Quality Control Mechanism

As on 31.01.2018

Sl. No.	Name of the State	Tier-I : TPIA (Third Party Inspection Agency)		Tier-II : RQM (REC Quality Monitoring)		Tier-III : NQM (National Quality Monitoring)	
		Scope	No. of Villages Inspected	Scope	No. of Villages Inspected	Scope	No. of Villages Inspected
1	Assam	5635	307	2254	96	113	0
2	Bihar	12380	3972	4952	878	247	28
3	Chhattisgarh	1618	1932	647	650	32	32
4	J&K	104	0	41	0	2	0
5	Jharkhand	9046	0	3619	0	181	0
6	Karnataka	4603	2038	1841	257	91	15
7	MP	13091	13987	5236	2986	262	123
8	Manipur	898	42	359	13	19	0
9	Mizoram	0	19	0	0	0	0
10	Nagaland	417	0	167	8	11	0
11	Orissa	22083	3074	8833	400	442	25
12	Rajasthan	12699	7245	5079	2055	253	128
13	Tripura	402	240	161	112	8	2
14	Uttar Pradesh	34589	19889	13835	3177	682	229
15	West Bengal	2816	3145	1127	1108	56	39
Total		120378	55890	48151	11740	2399	621

* TPIA Reports from some of the states are awaited

** No major deficiencies observed, only minor deficiencies like tilting of Poles , missing danger plates, missing Barbed wire, missing piercing connector are observed.